Medical Scale Maintenance



Inspect the entire scale for any obvious signs of damage.



Check the AC adapter for

cracked, frayed cords or

broken, bent prongs.



Change batteries regularly to avoid leaks.

Cleaning Your Scale



Use mild soap and water to clean externally with a damp cloth.



Do not submerge the scale in liquid.



Avoid using Isopropyl alcohol to clean the display surface.

Checking Your Scale



Use NIST Certified test weights to check your scale for accuracy.



Check your scale using 10% of the scale's capacity.



Do not shock load or drop weights onto the scale.

